

Listado nº: 17

**Coordenadas digitalizadas de los puntos de control - hoja (926) 1-2 -
digitalización nº 7**

429917.2587	4201618.9769	425577.1925	4197890.0545
429685.0032	4201448.7602	426803.4659	4197987.3757
429688.3522	4201408.7934	427093.0680	4197878.8644
429666.6214	4201337.6616	427186.9264	4197883.7070
430089.2655	4200872.9772	428600.7309	4197549.8610
430798.9699	4200460.8121	430850.2509	4197452.6205
430776.3846	4200420.5281	430793.9393	4197767.0077
431141.1036	4200669.1704	430721.9851	4198104.2606
431292.5413	4201441.4922	430620.0743	4198256.6813
427445.2701	4201488.5459	430603.3429	4198265.9037
427240.8071	4201472.9167	430963.1453	4198323.9616
426509.6480	4201329.7707	430968.3044	4198338.0809
426487.8280	4201322.8540	430879.7707	4198327.0953
426470.5702	4201310.8412	430789.1606	4198308.0353
426116.4218	4201261.4475	430381.3924	4198604.2464
426535.1304	4200798.1901	430238.5197	4198799.4352
426533.7866	4200350.8258	430197.1186	4199048.4916
426502.7283	4200199.2414	430169.7121	4199444.5761
426165.2219	4199324.8089	430862.7702	4199733.8002
426146.4588	4199335.5814	430818.1186	4199848.3904
426045.3742	4199162.7759	430876.5466	4199742.8009
425927.5268	4198961.2532	431045.3083	4199607.2088
426379.0434	4199648.5685	431617.7388	4199476.7972
426824.5241	4199716.9946	431631.4907	4199475.6811
426906.6833	4199679.9229	431444.0391	4198500.5146
426942.1954	4199679.1429	431503.1634	4198046.2296
427118.4198	4199927.7867	431486.5544	4198001.2738
427597.0286	4200202.9439	431446.8140	4197926.6065
427699.1547	4200412.1791	431469.1879	4197919.3476
427805.8578	4200636.5614	431420.7847	4197920.7232
427956.6941	4200855.5424	431317.6626	4197741.6811
428203.5810	4200925.1038	431277.5111	4197681.7060
428183.4635	4201063.7845	431209.9543	4197562.6733
428172.8177	4201069.9291	431246.8649	4197595.3206
428253.8096	4201193.7184	431217.5063	4197548.9407
428374.2938	4201381.9377	431182.1379	4197366.3519
428470.5263	4201406.5186	431701.5924	4197087.4202
428514.0491	4201463.8408	431719.7403	4197133.8841
428517.3820	4201420.8405	432044.9130	4197216.5435
428457.6364	4201469.3067	428708.0690	4200166.5763
428830.9648	4201681.9801	428267.6289	4200148.5412
428837.0398	4201387.1707	428258.9318	4200138.4924
428843.7992	4200353.1680	428238.2817	4200369.1964
428832.3868	4200020.5657	428151.6728	4200337.4672
429135.2413	4199982.4675	428143.6226	4200353.7049
428967.9200	4199976.6048	428827.5311	4200160.6524
428861.1404	4199397.4566	428762.3123	4199362.7826
429225.4922	4199450.4254	428487.0133	4199322.8180
430231.7738	4199449.6868	428040.9081	4199291.1728
425714.3833	4198179.9920	428050.6088	4199298.6863